






## Cross Slide Recess Attachments / Face Grooving



Tool Feeds Into the part from the cross slide



As Slide Continues to Feed, Draw Bar Shifts the tool into the Groove



Slide Retracts and Springs return the tool to original position



- **Designed and Manufactured for Acmes, New Britains, Wickmans, and more**
- **Mounts on Cross Slide,**
- **Unit can be purchased to feed toward the spindle or away from the spindle**
- **Provides a solution to cutting grooves, trepans, and under cuts**
- **Contact BME for Pricing and Availability**

[www.bmeattachments.com](http://www.bmeattachments.com)

3763 Lapeer Avenue, Suite 2E – Port Huron, MI 48060

Office 810.937.2974 / Fax 810.937.2975

